

10114: LEAD SAFE MAMA LLC

Inspection Summary

<b>Facility</b>	LEAD SAFE MAMA LLC (10114)	<b>Interviewee</b>	
<b>Address</b>	7933 SE 15th AVENUE PORTLAND OR 97202	<b>Inspector 1</b>	Rama Wusirika (971) 673-0490 RAMA.K.WUSIRIKA@oha.oregon.gov
<b>RPS Program</b>	XRay	<b>Inspector 2</b>	
<b>Form Type</b>	Non-Healing Arts Radiation Generating Devices		
<b>Inspection Type</b>	Routine		
<b>Date of Inspection</b>	06/08/2026		

10114: LEAD SAFE MAMA LLC

Violations

No item of noncompliance noted.

10114: LEAD SAFE MAMA LLC

Registrant's Acknowledgement

The Oregon Health Authority compliance inspector has explained the items identified in this report and I understand.

**Date:** June 8, 2026

**Print Name and Title:** Tamara Elise Rubin - Owner, ,

**Signature:**



**Oregon Health Authority Compliance Inspector:**

